

# 2021 Land Rover Range Rover

P525 Fifty L405 MY21.5 4X4 Dual Range

**\$119,888**

EGC - Excluding Government Charges



**Enquire Now**

Scan the QR code below  
for more information



|                                                                                                                                 |                                                                                                                             |                                                                                                             |                                                                                                                                    |
|---------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------|
|  Year<br><b>2021</b>                          |  Body<br><b>SUV</b>                      |  Colour<br><b>GOLD</b>   |  Transmission<br><b>8 SP Sports Automatic</b> |
|  Engine<br><b>5.0 L</b>                       |  Kilometres<br><b>77000 Kms</b>          |  Stock #<br><b>Q4049</b> |  Drive Type<br><b>4X4 Dual Range</b>          |
|  Fuel System<br><b>8 Cyl Direct Injection</b> |  VIN #<br><b>SAL-<br/>GA2AE7MA428058</b> |  Reg #<br><b>GCL49Q</b>  |                                                                                                                                    |

| FIFTY EDITION | PANORAMIC SUNROOF | MASSAGE SEATS |

\\CLEAR MATTE WRAP!!



**McCarroll's RAM Artarmon**  
**Call us on 1300 187 023**

403 Pacific Highway, Artarmon, NSW, 2064

Every effort has been made to ensure the accuracy of the information above, however, errors may occur.